



Alloy Excess Stock

Location	Grade	Shape	Dimension 1	Dimension 2	Dimension 3	Dimension 4	Quantity
11D	4130	Flat	0.125	2	72		1
11D	4130	Round	0.188	72		CD, Norm	1
11G	4130	Round	0.313	24		CD, Norm	1
11D	4130	Round	0.375	72		CD, Norm	4
2B	4130	Round	4.25	1.625		N	1
2B	4130	Round	4.25	1.75		N	1
2B	4130	Round	4.5	1.625		N	1
2C	4130	Round	6.25	3		RT & Norm	1
14	4130	Sheet	0.08	1.75	12	CR, Annealed	1
3C	4130	Sheet	0.08	1.75	24.5	CR, Annealed	40
14	4130	Sheet	0.08	2.5	24	CR, Annealed	1
M	4130	Sheet	0.08	24	36	CR, Annealed	1
14	4130	Sheet	0.125	12	26.5		1
14	4130	Sheet	0.188	36	72		1
D3	4130	Tube	0.75	1.5	0.049	61.25	4
2A	4140	Flat	0.093	3	16	Prec. Ground	1
2A	4140	Flat	0.188	5	9.875	Prec. Ground	1
2A	4140	Flat	0.25	1.5	12"	Prec. Ground	2
12H	4140	Hex	0.5	72		CD, AN	8
12G	4140	Round	0.25	72		HT	16
12G	4140	Round	0.313	60		CD, AN	1
12H	4140	Square	0.5	72		HR, HT	10
12H	4140	Square	1.125	72		CD, AN	2
2C	4142	Flat	0.5	2.5	6.625	HT	1
11G	4142	Flat	0.75	1	30.5	HT	1
2C	4142	Square	1	12		HT	1
3C	4340	Flat	1.25	1.5	22	N&T	1
2C	4340	Plate	0.625	5.25	5.5	BG to .625	5
2C	8620	Plate	0.25	2.5	24		2
2C	8620	Round	2.5	6		HR AN	1
2C	8620	Round	4.75	3.5			1
2C	9310	Round	2.125	2.75		Vac Melt	1
12D	9310	Round	2.125	39		Vac Melt	1
12D	9310	Round	2.125	45		Vac Melt	1