



Copper Excess Stock

Location	Grade	Shape	Dimension 1	Dimension 2	Dimension 3	Dimension 4	Quantity
3B	101	Plate	0.25	10.25	17.25		2
12A	101	Round	0.125	72			2
12B	101	Round	0.375	47			19
4	101	Sheet	0.05	36	48	Not Deep Draw	1
3B	101	Sheet	0.063	2	4		1
3B	101	Sheet	0.063	2	12		4
3B	101	Sheet	0.125	1.75	4		1
3B	101	Sheet	0.125	2.5	6		1
3B	101	Tube	0.375	0.032	17		1
3B	101	Tube	0.375	0.032	35		1
12B	101	Tube	0.5	0.063	72		1
12B	101	Tube	1	0.125	72		1
12B	102	Tube	0.84	0.107	19.5		1
12B	102	Tube	0.84	0.107	49.75		1
3B	110	Round	0.188	24			5
3B	110	Round	0.188	28			3
3B	110	Round	0.188	31.5			12
3B	110	Round	0.188	33.25			17
12A	110	Round	0.375	48			14
12A	110	Round	0.375	48			10
12B	110	Round	0.375	48			14
3B	110	Round	0.438	34			1
3B	110	Round	0.438	36			10
12A	110	Round	0.438	46.5			20
12A	110	Round	0.438	47			20
12B	110	Round	0.438	47			20
12A	110	Round	0.438	48			12
3B	110	Round	0.5	24			6
3B	110	Round	0.5	35			12
7	110	Sheet	0.032	4	14.375		1
7	110	Sheet	0.032	6	14.375		1
7	110	Sheet	0.032	36	81.5		1
3B	110	Sheet	0.05	1.63	2.75		247
3B	110	Square	0.25	36			10
3B	110	Square	1	35			48
3B	122	Tube	0.375	0.03	36		5



Copper Excess Stock

Location	Grade	Shape	Dimension 1	Dimension 2	Dimension 3	Dimension 4	Quantity
3B	122	Tube	0.375	0.032	23		15
3B	122	Tube	0.375	0.065	25.75		1
3B	122	Pipe	2.875	0.188	7		1
3B	150	Flat	0.313	0.5	12		1
12A	173	Round	0.125	72			1
3B	173	Round	0.5	24			1
3B	17510	Square	2	10		Cl. 3 Bery.	1
3B	182	Plate	0.5	0.75	36	Class 2 Chrom	1
12C	18200	Round	0.25	48		Cl. 2 Chrom	2
12C	18200	Round	0.25	36		Cl. 2 Chrom	1
3B	Beryllium	Round	1.25	18		MoldMax	1
7	Copper	Sheet	0.025	6	12		3
12C	Copper	Tube	0.25	0.063	84		10