



### Tool Steel Excess Stock

Location	Grade	Shape	Dimension 1	Dimension 2	Dimension 3	Dimension 4	Quantity
B1	A2	Flat	1.25	1.25	24		1
3A	A2	Flat Ground	0.25	1	4.625		4
2A	A2	Flat Ground	0.375	3	16.5		1
2A	A2	Flat Ground	0.5	2.5	16.25		1
2A/2B	A2	Flat Ground	0.5	3	5.5		13
3A	A2	Flat Ground	0.625	1.25	16.5		1
3A	A2	Flat Ground	0.75	1.25	6.5		3
3A	A2	Flat Ground	0.75	1	7		1
2A	A2	Flat Ground	0.75	2	12		1
3A	A2	Flat Ground	1	1.25	4.5		3
2A	A2	Flat Ground	1	10	2.5		1
3A	A2	Round	0.093	18			17
B3	A2	Round	0.5	4.75			1
3A	A2	Round	0.625	11.875			1
3A	A2	Round	0.625	20.25			1
3A	A2	Round	0.625	36			2
3A	A2	Round	0.75	36			1
2B	A2	Round	1.75	2.25			17
3A	A2	Round	2	2.188			1
2B	A2	Round	3.25	2.188			1
2B	A2	Round	3.25	4.25			1
B3	A2	Round	4.5	0.5			1
B3	A2	Round	5	1.25			1
B3	A2	Round	5.25	0.375			1
3A	A6	Flat Ground	0.375	3	17.25		1
3A	D2	Flat	0.5	2	2.25		1
2C	D2	Flat	1	2.188	2.438		1
3A	D2	Flat Ground	0.094	0.5	11.75		1
2A	D2	Round	5	4.5			1
2A	O1	Flat	0.438	1	8		1
2A	O1	Flat	0.5	0.75	21		1
2A	O1	Flat	0.563	1	5		1
3A	O1	Flat Ground	0.063	0.5	18		6
2A	O1	Flat Ground	0.063	1	10.5		1
3A	O1	Flat Ground	0.125	0.5	12		1
3A	O1	Flat Ground	0.14	0.75	18		1
3A	O1	Flat Ground	0.25	0.375	18		2
B3	O1	Flat Ground	0.25	8	11		1
3A	O1	Flat Ground	0.5	1.25	18		1



### Tool Steel Excess Stock

Location	Grade	Shape	Dimension 1	Dimension 2	Dimension 3	Dimension 4	Quantity
3A	O1	Round	0.125	18			1
3A	O1	Round	0.125	36			9
3A	O1	Round	0.156	18			1
3A	O1	Round	0.188	36			7
3A	O1	Round	0.218	18			1
3A	O1	Round	0.218	36			1
3A	O1	Round	0.281	18			1
3A	O1	Round	0.313	18			3
3A	O1	Round	0.313	36			1
3A	O1	Round	0.328	18			7
3A	O1	Round	0.375	18			2
3A	O1	Round	0.563	18			1
3A	O1	Round	0.563	36			1
3A	O1	Round	0.625	12			10
3A	O1	Round	0.625	36			1
3A	O1	Round	0.719	56.75			1
3A	O1	Round	0.812	18			1
3A	O1	Round	0.812	36			3
3A	O1	Round	0.875	11.75			1
3A	O1	Round	0.875	18			1
3A	O1	Round	1.125	5.75			1
3A	O1	Round	1.25	6			1
3A	O1	Round	2	6			1
3A	O1	Round	3	1.25			1
3A	O1	Round	12mm	24			1
3A	O1	Square	1	36			1
3A	P20	Round	0.5	12			1
3A	P20	Round	0.75	23.875			1
2B	S7	Flat Ground	0.625	2	12		1
3A	S7	Flat	0.75	1.75	2.625		11
3A	S7	Round	0.5	18			1
3A	S7	Round	0.5	29.5			1
3A	S7	Round	0.75	3.5			1
3A	S7	Round	0.75	11.25			1
3A	S7	Round	1	5.5			1
3A	S7	Round	1.125	2.75			1
3A	S7	Round	1.5	22.375			1
3A	S7	Round	1.75	5.75			1

Tool Steel Excess Stock

3A	S7	Round	4.5	1.5			1
3A	S7	Round	5	0.875			1